


ANNEX I: Mechanical Photographic Report

Annex: Photographic Report

The Photographic report will be split in the main opened areas, which will be pointed in the site plant layout.

Temporary Cofferdam Area:



*Temporary Sheet Piles were Erected in Sea Water Intake
North Side for Commissioning Purpose*



*Temporary Sheet Piles were Erected in Sea Water Intake
North Side for Commissioning Purpose*



*Temporary Sheet Piles were Erected in Sea Water Intake
North Side for Commissioning Purpose*

Progress Report
PR-CHEN-033

BEFESA Agua S.A.U.


100 MLD Desal Plant

ANNEX II: Civil Photographic Report

Annex: Photographic Report

The Photographic report will be split in the main opened areas, which will be pointed in the site plant layout.

Temporary Cofferdam Area :



*Temporary Cofferdam Work Completed and
for Commissioning Work*



Temporary Lagoon Work Completed for Sea Water Intake



Temporary Cofferdam Work Completed for Sea Water Intake

Progress Report
PR-CHEN-033

BEFESA Agua S.A.U.

100 MLD Desal Plant

ANNEX IV: Marine Photographic Report

Photographic Report for Marine Works

COFFERDAM



BRACING START IN THE DEBRIS REMOVAL COFFERDAM



BRACING FINISH THE DEBRIS REMOVAL COFFERADAM



COFFERDAM READY FOR REMOVAL DEBRIS OPERATIONS START



*AIR DREDGE READY FOR DREDGING INSIDE
COFFERDAM DEBRIS REMOVAL*



*EXTRA BARCING IN THE REMOVAL DEBRIS
COFFERDAM.*

ALTERNATIVE INTAKE COFFERDAM



WATER LEVEL CONTROL



ENTRANCE LAKE CONTROL